



**LEGEND**

- MONITORING WELL
- WATER SUPPLY WELL
- WELL DEPTH BELOW GROUND SURFACE
- VACANT PROPERTY
- 1,4 DIOXANE EXCEEDS 0.3 ug/L [PROPOSED MCP METHOD 1 GW-1 STANDARD]
- 1,4 DIOXANE DETECTED AT OR BELOW 0.3 ug/L
- 1,4 DIOXANE NOT DETECTED
- PROPERTY NOT TESTED

SOURCE: "ENVIRONMENTAL MONITORING LANDFILL MONITORING PLAN" PREPARED FOR EASTHAM LANDFILL, OLD ORCHARD RD, EASTHAM, MA, BY BENNETT ENVIRONMENTAL ASSOCIATES, INC., BREWSTER, MA, DATED 6/17/13.

		273 West Main Street Norton, MA 02766 (508) 228-1800 (508) 228-1811 fax info@esm-inc.com	
		GAUGING DATE:	DRAWING DATE:
	10/16/13	EASTHAM LANDFILL	
<b>SITE MAP</b>			
CLIENT:	TOWN OF EASTHAM		PM:
LOCATION:	OLD ORCHARD ROAD EASTHAM, MASSACHUSETTS		LSP: DH
RTN:	DWG:	PROJECT NO.:	FIGURE:
4-24301	DMR	2013-027	1